
High Level Sewershed

Run Summary —								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-126	Smoke	10/20/2008	ADS/TM	S13II_032MH	Dry	Yes	901.03	



High Level Sewershed

Run Summary —								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-126	Smoke	10/20/2008	ADS/TM	S13II_032MH	Dry	Yes	901.03	

Isolated Pipes Length Diameter Pipe ID **Upstream MH Downstream MH** (ft) (In) S13II_032G1 S13II_032MH S13II_025MH 249.7878 8 S11II_024G1 S11II_024MH S11II_030MH 42.39579 8 S11II_030G1 S11II_030MH S13II_032MH 251.7740 8 S11II_001G1 S11II_001MH S11II_042MH 173.6184 8 S11II_003G1 S11II_003MH S11II_030MH 183.4506 8

Observations & Photos

Obs_ID S1028-126-OB01 **Address** 1816 Poplar Grove St

Status Private
Source Downspout

Location Driveway

Nearest MH \$13II_025MH

Comments Smoke from downspout in side of building at driveway edge. 1816 Poplar Grove St.



Picture \S1028-126-OB01-P01.jpg

Comments Side of house, 1816 Poplar Grove

St.

Obs_ID S1028-126-OB02 **Address** 2917 North Ave

Status Private **Source** Cleanout

Location Paved asphalt **Nearest MH** S13II_032MH

Comments Smoke from cleanout in parking lot behind

house. 2917 North Ave.



Picture \S1028-126-OB02-P01.jpg

Comments Back of house, 2917 North Ave.

High Level Sewershed

_	_		
Run	Sur	nm	arv

Kun Summary								
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length	
S1028-126	Smoke	10/20/2008	ADS/TM	S13II_032MH	Dry	Yes	901.03	

Obs_ID S1028-126-OB03 **Obs_ID** S1028-126-OB04 Address 2919 North Ave Address 2921 North Ave Status Private Status Private Source Cleanout Source Cleanout Location Paved asphalt Location Paved asphalt Nearest MH S13II_032MH Nearest MH S13II_032MH

Smoke from cleanout in parking lot behind Smoke from cleanout in parking lot behind Comments Comments house. 2919 North Ave.

house. 2921 North Ave.



Picture \S1028-126-OB03-P01.jpg

Comments Back of house, 2919 North Ave. Comments Back of house, 2921 North Ave.

Obs_ID S1028-126-OB05 **Obs_ID** S1028-126-OB06 Address 2929 North Ave Address 2939 North Ave Status Private Status Private Cleanout Source Source Cleanout Location Location

Paved asphalt Paved asphalt Nearest MH S13II_032MH Nearest MH S11II_030MH Smoke from cleanout in parking lot behind **Comments**

Smoke from cleanout in parking lot behind **Comments** house. 2929 North Ave. house. 2939 North Ave.

Picture \S1028-126-OB05-P01.jpg

Comments Back of house, 2929 North Ave.



Picture \S1028-126-OB06-P01.jpg

Picture \S1028-126-OB04-P01.jpg

Comments Back of house, 2939 North Ave.

High Level Sewershed

Run	Summarv	,
Ruii	Sullilliai v	

	,	Data					Total
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-126	Smoke	10/20/2008	ADS/TM	S13II_032MH	Dry	Yes	901.03

Obs_ID S1028-126-OB07 **Obs_ID** S1028-126-OB08 Address 3010 Westwood Ave Address 3022 Westwood Ave Status Private Status Private Source Other Source Cleanout Location Yard - back Location Yard - back Nearest MH S11II_024MH Nearest MH S11II_001MH

Smoke from underneath pile of debris in back Smoke from cleanout in back yard. 3022 Comments yard. 3010 Westwood Ave.

Westwood Ave.



Picture \S1028-126-OB07-P01.jpg

Comments Back of house, 3010 Westwood Comments Back of house, 3022 Westwood



Picture \S1028-126-OB08-P01.jpg